

Machinery for the Woodworking, Stone, **Glass, Plastic, and Metalworking Industries** 



Date :	04/25/2024 - 7:38 PM *
EXF # :	EU-281177
Category :	EDGEBANDERS-UNDER \$25,000
Brand / Model :	HOMAG "KL 75/A20"
Machine Type :	EDGEBANDER
Year of Mfg. :	2001
Condition :	Cleaned & Checked
Elect / Voltage :	460 V, 60 Cy, 3 Ph.
Special Note :	Great Value

Please ask me

800-374-5009 ext. 377 Intl. +1 704-841-2001 ext. 377 Ed.Webb@exfactory.com

Ed Webb

FOB / Region :	MIDWEST
Appr. Repl. Cost. :	\$ 130,000
Price :	\$ 12,900 *
Comment :	A little bit of work is going to make it look like
Leasing :	Lease for \$ 262/Mo. at NCL

\* Pricing is valid at the time of printing and subject to change at any time.

## **Description**:

HOMAG OPTIMAT KL-75 / A20 EDGEBANDER

0.4 - 20 mm (3/4") Thickness edgebanding cap., 70 mm min. panel thickness.

Equipped with: Automatic edge feed magazine for coil, HPL & strip stock; "Hot Melt" glue system with QA34 Quickmelt unit, with reversible glue roll applicator; pneumatically controlled pressure roll section with 7 pressure rollers.

- Workstations: Double motor front & rear end trim, straight & chamfer trimming (0.5 HP 10,400 RPM ea. ٠ motor).
- Top & Bottom rough trims (2 HP 11,500 RPM ea. motor).
- Top & Bottom fine trims, tiltable 0° 30° (0.5 HP 10,980 RPM ea. motor); open space for workstation.
- Adjustable top and bottom glue scraper.

## Sales - Liquidations - Auctions - Appraisals - Consulting



- Electronic Height adjustment for Top pressure beam with double V-belts, 80 mm wide Heavy Duty feed chain w/rubber pads.
- Feed speed variable up to 35 MPM.
- Complete with: SIKO Digital adjustments on T & B Flush and Fine Trim.
- Homatic NC21 Controller, Fixed position Outrigger panel support, insulated sound cabins w/interior and overhead lighting for all trim workstations.
- Includes Owners Manual and the Electrical Schematics.

**NOTE:** Suggested replacement parts needed, as noted by our technician - all the track pads, the hold-down belt, the pressure roller, and likely a glue pot rebuild. Estimated cost for these parts, not including labor is \$5600. The replacement of these parts is NOT included in the machine price.

Sales - Liquidations - Auctions - Appraisals - Consulting